




Molten Material

- Keep away from furnace areas unless your job requires you to be there
- Maintain safety clearances when metal is being poured
- Appropriate PPE MUST be worn in furnace areas
- Do not touch cast products or moulds in the foundry area as they may still be very hot
- Never look into a furnace without proper eye protection
- Keep clear when ladles of molten material are being transported
- Persons with heart pacemakers must not enter the furnace melting areas due to high magnetic fields
- Pregnant women must not enter the furnace melting areas due to high magnetic fields



Keep clear if you're not supposed to be here



PROUD TO BELONG
PROUD TO BE SAFE



PROUD TO BELONG
PROUD TO BE SAFE

